





⚡ 220 - 240 V loser Netzanschluss ( laut VDE 0100 Teil 701 )



|              | 1 | 2 | 3 | 4 | H2   | A1  |
|--------------|---|---|---|---|------|-----|
| 5144 00 / 01 | X |   | X | X | 1010 | 590 |
| 5148 00 / 01 | X | X | X | X | 1010 | 590 |
| 5149 00 / 01 | X | X | X | X | 1010 | 590 |
| 5149 10 / 11 | X |   |   |   | 1010 | 590 |
| 5151 00 / 01 | X | X | X | X | 1010 | 590 |
| 5151 10 / 11 | X |   |   | X | 1010 | 590 |
| 5154 00 / 01 | X | X |   |   | 1010 | 590 |
| 4110 45      | X |   |   | X | 1090 | 600 |
| 4110 60      | X | X |   |   | 1090 | 600 |
| 4125 40 / 41 | X |   | X | X | 1070 | 630 |
| 4126 60 / 61 | X |   |   | X | 1070 | 630 |
| 4127 60 / 61 | X |   |   |   | 1070 | 630 |
| 4132 60 / 61 | X |   | X |   | 1070 | 630 |
| 4179 43      | X |   | X | X | 1010 | 590 |
| 4198 61      | X |   |   | X | 1010 | 590 |
| 4172 58      | X | X |   |   | 1010 | 590 |
| 4178 41      | X |   |   |   | 1010 | 590 |
| 4A1840       | X |   | X | X | 1090 | 590 |
| 4A2138       | X | X |   | X | 1090 | 590 |
| 4A1956       | X | X | X | X | 1090 | 590 |
| 4A2056       | X | X | X | X | 1090 | 590 |